

Memorandum



Henault

99
220.1

747

DATE : December 14, 1976
TO : Bob Reineke
FROM : Pete Henault
SUBJECT : CLEAN UP OF PCBS AT SOUTH SERVICE CENTER

In my December 8, 1976, report to the Superintendent regarding PCBs at the South Service Center, I suggested that it may be appropriate to clean out all catch basins within the South Service Center, label and store them, and then sample them as soon as possible to see if they do indeed contain PCBs.

Before I can make a more detailed recommendation to the Superintendent on this matter, it is necessary that we develop some cost data associated with this exercise. Would you therefore please determine how much it would cost to make a number of tests for PCBs. Also, what is the cost of cleaning up all catch basins and storing the material? You should work with Joe Recchi on this matter to determine who can assist you in determining the necessary information.

PBH:ct

cc: Recchi
Henault